

Aurora





# 100% LED lighting 98% Efficient Hybrid Tankless Water Heater 95.5% Efficient Furnace Non-Toxic Paint 100% Natural Wool carpet & pad

GreenPath Master Certified Home Unparalleled NEXT GEN Construction Incomparable Indoor Air Quality

• Marvin Integrity Fiberglass Exterior/Wood Interior Windows

Ultra Energy Efficient Thermal Mass Insulation System

Breathtaking Features

- Appalachian Hardwood Cherry Floors w/ 20yr warranty
- Tumbled Travertine Tile Bathroom floors
- Authentic Craftsman Amenities & Style
- Covered porches w/ Brazilian Walnut decking
- LP Smartside siding w/ 20 year paint warranty
- Soapstone & Black Walnut Countertops
- Beautiful Clawfoot Slipper Tub
- Nest WiFi Thermostat
- Electrolux Induction Dual Oven Range
- Delta Victorian Faucets
- Solid Wood Enameled Trim
- Pressurized HET Dual Flush Toilets
- Professionally Designed Landscaping

• Nostalgic Cobblestone Lake homesite

\$349,900

# Aurora

# Additional Features

- **VOC Absorbing Materials**
- Natural Travertine Stone Floor in Laundry Room
- Front Load Washer & Dryer
- Laundry Cabinets with Deep Sink
- Gas Fireplace
- Travertine Fireplace Surround & Wood Mantle
- Ultra Quiet Panasonic® Bath Exhaust Fans
- Insulated & Sheetrocked Garage









**HERS Index** 

This home is 58% more energy efficient than the HERS reference home built to code.

# **Home Performance Report**

MN GREEN PATH | WWW.MNGREENPATH.ORG



These results reflect Air Changes per Hour of measured air flow in relation to the building volume while the building is maintained at a

Home Address:

15561 Dunberry Way, Apple Valley MN 55124 Square Feet: 1430 | Bedrooms: 3 | Baths: 2 **Builder: Endres Custom Homes** 

www.endrescustomhomes.com

certified

## **Energy Efficiency**

- HERS Index 42
- Blower door test result of ≤0.3 cfm per sa ft ENERGY STAR Certified Clothes Washer and Refrigerator
- Energy efficient lighting in 100% of whole
- house (CFL/LED)
  High Efficiency Exterior Wall Insulation (R-21)
- High Efficiency Foundation Insulation (R-20) Foam Insulation installed around outside window and door units
- Rigid foam in all exterior walls (R-20)
- Programmable thermostat
- Under-slab (subslab) foam insulation (R-10) Systems approach to home design used
- Bottom plates of exterior walls sealed to
- subfloor
- Foundation and mudsill sealed
- Air conditioning unit properly installed
- No wood burning fireplaces present inside the thermal envelope
- Induction cook top installed
- High-efficiency furnace (95+) installed
- High-efficiency boiler 98+) installed
- Electronically commutated (ECM) motor
- Special Feature: Remote process for

## **Indoor Environmental** Quality

- Home ventilated mechanically 48 hours prior to occupancy
- Gas combustion equipment sealed/direct
- Attached garage sealed: air barrier, common walls, ceiling, and penetrations all sealed prior to insulation

Capillary breaks for moisture management: between top of footings and bottom of foundation wall: below slabs: and where cementitious products connect to framing material

pressure difference of

50 Pascals.

ACH50

- Building cavities not used as part of duct work for supplies and returns
- Foundation waterproofed from footing to sill
- Patio slabs, walks, and driveway sloped minimum 1/8" per foot away from house
- Garage floors sloped minimum 1/8" per foot toward main vehicle entry
- Doorway or integrated floor drains installed 4" min perforated foundation drains with 3/4' of gravel and filter fabric installed at OUTSIDE perimeter of footings
- 4" min perforated foundation drains with 3/4" of gravel and filter fabric installed at INSIDE perimeter of footings
- Drainage plane and air/drainage space behind siding
- Recessed light fixtures sealed to drywall with gasket, caulk, or foam
- Heat Recovery Ventilator (HRV) or Energy Recovery Ventilator (ERV) installed
- Air filters are HEPA or better performing, with MERV rating of 12-15 Ductwork sealed with water-based, low-VOC
- (<30 a/l) mastic HVAC contractor verified that rooms and
- zones have balanced air flow Building materials stored on-site protected from weather exposure
- Exterior envelope sealed using gasket or oustical sealant at all intersections
- Basement has foundation drainage system inside and outside with sump pump, or tied to a drainage outlet
- Certified low-VOC or no-VOC interior paints and finishes used
- Carpet, adhesives, and cushion qualify for CRI Green Label Plus or Green Label Testing program
- Local exhaust ventilation to outdoors installed for baths, kitchen, clothes dryers, central vacuum system, etc

- Central forced-air HVAC systems have minimum MERV 8 filter, no filter bypass, and no ozone generators
- Supply boots sealed to floor or wall
- All materials containing adhesives or paint are low-emitting or low-formaldehyde
- Capillary break installed at footing, below slab, and at cementious products and framing connection
- Special Feature: Air-renew VOC absorbent sheetrock used

#### **Water Conservation**

- All lavatory faucets and showerheads lowflow (1.5 gallon/minute)
- Landscape plan promotes water absorption
- Irrigation system design zones turf and bedding areas separately
- Installed drip irrigation system has moisture/rain sensor
- Roof water drainage system installed
- Hot water recirculating pump installed
- NSF-certified water filters installed on drinking water sources; dual flush total composting low water
- Minimum 3" of mulch applied to all planting beds
- Showers have no more than one shower head
- No garbage disposal installed
- Irrigation system designed by EPA water-sense certified professional

## **Resource Management**

- FSC/SFI/CSA Certified lumber in 65% of
- Construction waste recycled
- Decking or patio material made from renewable wood content
- Recycled erosion control materials used for silt fencing
- Recycled concrete, asphalt, or glass used for base or fill

- Framing utilized two-stud corners with drywall clips
- Insulation with minimum 20% recycled content used for at least 50% of the insulation (e.g., all walls, or only attic)
- Construction waste sorted on or off site and recycled as appropriate
- Recycling center installed with homeowner use with a minimum of two sorting bins
- Reusable footings and foundation forms used 90% of lumber in home is SFI/FSC/CSA
- Wood-framed panels or remote construction were used
- Roofing material either lifetime-warranted (steel), or easily recyclable
- Flexible ductwork installed without excess coils or loops
- Three of the following items are 50% locally sourced (within 500 miles): cabinets, interior doors and trim, millwork, windows, flooring, shingles/roofing, PEX tubing, countertops
- Materials installed which protect waterproof membrane and function as hydrostatic pressure release
- Special Feature: 2x4 construction used, sheet rock used for exterior structure sheeting

#### Land Use

- Erosion control present during construction
  - Home built on infill site
- Home built in area where housing density averages more than 4 single family homés per acre
- Home within 1/2 mile of local businesses
- No heritage trees removed on home site Home within 1/2 mile of public
- transportation access Home within 5 miles of park-and-ride
- Home within 1/2 mile of bike route Efforts taken to restore ecosystem damaged
- in construction No trees removed from construction site





